



TECH NOTE

AUTOMOTIVE – SYNCHRONOUS BELT DRIVE SYSTEM

T1095, T1671 AND RELATED TENSIONERS

An OEM/OES upgrade has made timing belt T1095 and the associated tensioners T43064 (Fig. 1 left) or T43168 (Fig. 1 right) as well as timing kits TCK1095 and TCKWP1095, obsolete. They will no longer be installed on Renault K4M/K4J engines.



Fig. 1

Belt T1095 has been superseded by T1671, tensioner T43064 has been superseded by T43236 (Fig. 2 left) and tensioner T43168 has been superseded by T43238 (Fig. 2 right).



Fig. 2

All four tensioners appear to be identical, but there is an essential

operational difference. New generation tensioners T43236 and T43238 deliver less belt tension and can only be used with the new generation belt: T1671, construction designed specifically for this upgrade.

The old belt (T1095), old tensioners (T43064 and T43168) and kits from your inventory can still be installed on K4J/K4M applications manufactured before 2013. Old generation parts and new generation parts can't be mixed. The new belt (T1671) may be used on all K4M/K4J applications. However, it must only be used in conjunction with the new generation tensioners (T43236 and T43238) as found in Gates PowerGrip Timing Component Kits TCK1671 and TCKWP1671.

BULLETIN: TSB0021_AU

PART NUMBER:

- T1095
- T1671
- TCK1671
- TCKWP1671
- TCK1095
- TCKWP1095

MAKE:

- Renault

ENGINE:

- 1.4L 16V Petrol
- 1.6L 16V Petrol

YEAR:

- 1998-current

**ALWAYS CHECK THE GATES
ONLINE CATALOGUE FOR
CORRECT BELT/TENSIONER
APPLICATION AND USAGE.**

GATES AUSTRALIA PTY LTD

200 National Drive, Dandenong South VIC 3175
PH: +61 3 9797 9666 FAX: +61 3 9797 9600

WWW.GATES.COM/AU/EN.HTML
FOLLOW: GATES AUSTRALIA

