



TECH TIP

COOLING SYSTEM

BULLETIN TT005-15

- › MAKE:
All makes with a water pump
- › MODEL:
All models with a water pump
- › YEAR:
All years with a water pump
- › ENGINE:
All engines with a water pump

Water Pump Failure Signs

If during the course of an inspection the water pump is found to look like any of the below, Gates recommends properly flushing the system, filling the system with a new mixture of the correct coolant, and possibly replacing the water pump depending on the issues found.



DEPOSITS/CALCIUM BUILDUP




DEPOSITS/CALCIUM BUILDUP



RUST/CORROSION



RUST/CORROSION



DEPOSIT BUILDUP



RUST/CORROSION



CAVITATION / CORROSION



CAVITATION / CORROSION



CAVITATION / CORROSION



CAVITATION / CORROSION



CHEMICAL ETCHING



CORROSION

WITH OVER 100 YEARS OF EXPERIENCE,
GATES PRODUCTS ARE TRUSTED BY PROFESSIONAL
TECHNICIANS AROUND THE WORLD.

For more information, please contact our Technical Department
at 303.744.5651 or apateam@gates.com.
© 2017 Gates Corporation. All rights reserved.



GATES.COM

Follow GatesAuto

